



**GLASS KILN
FIRING SCHEDULE:**

FULL FUSE (1 - 12)

1	70	180
2	1000	60
3	1000	240
4	1225	30
5	1225	60
6	1480	10
7	1480	120
8	930	60
9	930	120
10	700	60
11	700	220
12	100	-121

SLUMP FUSE (13 - 20)

13	70	240
14	1250	90
15	1250	120
16	900	60
17	900	120
18	700	15
19	700	220
20	100	-121

TACK FUSE (21 - 28)

21	70	220
22	1200	30
23	1200	30
24	1320	120
25	900	60
26	900	120
27	700	200
28	100	-121